

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: City of Greenfield, Hancock County, Indiana

Community No.: 180084

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previous Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs) that will be affected by the preparation of the enclosed revised FIRM panel(s).

1. LOMRs and LOMAs Incorporated

The modifications effected by the LOMRs and LOMAs listed below have been reflected on the Preliminary copies of the revised FIRM panels. However, these LOMRs and LOMAs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMR	99-05-083P	09/30/1999	Broadway Village (Second Submittal)	180084 0001 C	18059C0134 D
LOMR	97-05-4248P	09/10/1998	Putter Ditch, Whitcomb Commons	180084 0009 C	18059C0149 D

2. LOMRs and LOMAs Not Incorporated

The modifications effected by the LOMRs and LOMAs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMR or LOMA issued had determined that the lot(s) or structure (s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMRs and LOMAs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single letter that reaffirms the validity of the previous LOMC.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	06-05-0708A	01/10/2006	Waterview Estates, Section 3, Lot 156; 109 Creekwood Drive	180084 0006 C	18059C0147 D
LOMA	06-05-0257A	12/29/2005	Bradley's Addition, Block 1, Lots 1 and 4; 18 Grant Street	180084 0005 C	18059C0147 D
LOMR-F	05-05-4628A	10/06/2005	Intersection of County Road 100 North and County Road 400 East	180084 0006 C	18059C0161 D
LOMA	05-05-0351A	11/17/2004	Sherwood Hills, Section 2, Lot 102; 1411 Sherwood	180084 0006 C	18059C0147 D

PRELIMINARY SUMMARY OF MAP ACTIONS (CONT'D)

2. LOMRs and LOMAs Not Incorporated (Cont'd)

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMR-F	05-05-0343A	11/15/2004	Brandywine Trace, Lot 1; 709 East McKenzie Road	180084 0006 C	18059C0147 D
LOMR-F	04-05-3376A	06/14/2004	Indigo Springs, Section 1, Lots 10 and 92 through 94	180084 0006 C	18059C0161 D
LOMA	04-05-1104A	01/14/2004	Indigo Springs, Section 1, Lots 4 through 24 and 41 through 71 and 92 through 98	180084 0006 C	18059C0161 D
LOMA	03-05-1166A	05/09/2003	Chandler Addition, Lot 62; 1227 and 1229 East 2 nd Street	180084 0006 C	18059C0147 D
LOMA	03-05-1169A	05/09/2003	Chandler Addition, Lot 63; 1221 and 1223 East 2 nd Street	180084 0006 C	18059C0147 D
LOMA	03-05-0733A	01/31/2003	Hill Grove Addition; 26 Valley Drive	180084 0006 C	18059C0147 D
LOMR-F	03-05-0109A	01/22/2003	Waterview Estates, Section 3, Lot 158; 201 Creekwood Drive	180084 0006 C	18059C0147 D
LOMR-F	03-05-0581A	12/27/2002	Copeland Farms, Section 1, Lots 21, 22, 31, 32, 34; 1730 Copeland Drive	180084 0005 C	18059C0147 D
LOMR-FW	03-05-0107A	11/27/2002	A Portion of Section 22, Township 16 North, Range 7 East; 2388 North 400 East	180084 0002 C	18059C0153 D
LOMR-F	02-05-4696A	11/06/2002	Sweetwater Farms, Section 3, Lots 130 through 135 and 142 through 147	180084 0006 C	18059C0161 D
LOMA	00-05-5074A	11/07/2000	Fairway Village Subdivision, Section 1, Lot 3; 2841 East Fairway Village Drive	180084 0010 C	18059C0163 D
LOMA	00-05-4888X	07/27/2000	Sherwood Hills Subdivision, Section 3, Lot 53; 1522 Sherwood Drive	180084 0006 C	18059C0147 D
LOMR-F	00-05-2488A	07/25/2000	Brandywine Village	180084 0002 C	18059C0134 D

PRELIMINARY SUMMARY OF MAP ACTIONS (CONT'D)

2. LOMRs and LOMAs Not Incorporated (Cont'd)

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMR-F	99-05-3604A	07/21/1999	Hickory Hill, Lot 1; 2020 North Hickory Boulevard	180084 0002 C	18059C0134 D
LOMA	99-05-3834A	06/02/1999	Waterview Estates, Section 3, Lot 115; 445 Waterview Boulevard	180084 0006 C	18059C0147 D
LOMA	99-05-578A	12/18/1998	Sherwood Hills, Third Section, Lot 96; 1521 Sherwood Drive	180084 0006 C	18059C0147 D
LOMA	98-05-5902A	09/16/1998	730 Oak Boulevard	180084 0005 C	18059C0147 D
LOMA	98-05-3218A	07/02/1998	Chandler's Addition, Lot 146; 327 Cherry Street	180084 0006 C	18059C0147 D
LOMR-F	97-05-1800A	07/17/1997	Waterview Estates, Lot 155, Section 3	180084 0006 C	18059C0147 D
LOMR-F	96-05-3030A	08/07/1996	Part of the Southwest quarter of Section 29	180084 0005 C	18059C0147 D
LOMR-F	95-05-1646A	08/24/1995	1763 James Boulevard	180084 0006 C	18059C0147 D
LOMA	92-05-008B	01/30/1992	Layne Crest Addition, Lot 132; 715 West Bond Avenue	180084 0005 C	18059C0147 D
LOMA	92-05-320B	05/08/1992	Part of the Northeast quarter of Section 24, Township 16 North, Range 7 East	180084 0006 C	18059C0161 D

PRELIMINARY SUMMARY OF MAP ACTIONS (CONT'D)

3. LOMRs and LOMAs Superseded

The modifications effected by the LOMRs and LOMAs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMRs and LOMAs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will Be Superseded
LOMR-F	97-05-2606A	07/02/1997	Sherwood Hills, 4 th Section, Lot 54; 1526 Sherwood Drive	1
LOMA	199107917FIA	07/02/1991	--	1
LOMA	199201019R05	01/29/1991	--	1
LOMA	91-05-1300W	01/29/1991	Chandler's Addition, Lots 15 and 16; 1208 East Main Street	1
LOMA	199103739FIA	03/17/1989	--	1
LOMA	89-05-1273W	03/17/1989	Sherwood Hills, 3 rd Section; 1518 Sherwood Drive	1
LOMA	82-05-1082W	12/01/1982	Sherwood Hills, Lot 47	1

¹ Insufficient information available to make a determination.
² Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
³ Lowest Ground Elevation is below the proposed Base Flood Elevation.
⁴ Revised hydrologic and hydraulic analyses.
⁵ Revised topographic information

4. LOMRs and LOMAs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. We will review the data previously submitted for the LOMR or LOMA requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
None					